

Certificate

to demonstrate the suitability of the user-company for manufacturing adhesive bonds in accordance with DIN 2304

The Company

3A Composites Mobility S.A.

with production site in

Ulica Inwestorow 6 PL-39-300 Mielec

has been certified in accordance with DIN 2304 for the following area of validity:

Design with bonded Parts Class S1

Process Planning with bonded Parts Class S1

Production of bonded Parts Class S1

Repairs of bonded Parts Class S1

Purchase, Trade and Assembling of bonded Parts Class S1

Supervisor in Charge:

Mr. Piotr Dabek, born on 1989-02-18, EAE

Deputy Supervisor in Charge:

Ms. Karolina Maziarz-Stokowska, born 1993-10-02, EAE

Other Supervisors:

Mr. Piotr Babula, born on 1990-06-02, EAS

Other supervisors see the back page.

Remarks:

This document is only valid in combination with the actual registration of the certificate in the Online-Register. For further remarks see the back page.

Certificate No.:

TC-K/2304/S1/N-2/2021/41

Validity:

2021 September 15th – 2024 September 14th

Issued on:

2021 September 15th

Changed on:

2023 April 06th



Thomas Richter, Head of the Certification Body



Other Supervisors:

Mr. Maciej Rzemien, born on 1990-04-26, EAS

Mr. Lukasz Zawadzki, born on January 1990-01-20, EAS.

Remarks

Classified bonded parts only have to be produced in the proven areas:

Bonding room H1 and H3.

General Regulations

The new application hast to be submitted to the certification body at least two month before the certificate expires if the suitability of the user-company shall be certificated furthermore.

Changes within the time of valitity of the certificate

If the adress of the user-company or company site, the class of the certificate, supervisors of the area of validity change, the certification body must be informed immediately. The certification body decides about the necessity of an inspection on the site and change of the certificate.

Withdrawal of the certification

Authority or the certification body can withdraw certification if:

- 1) There is a serious shortcoming in the execution of the adhesive bonding work as required by this standard;
- 2) There is a serious shortcoming in the supervision of the adhesive bonding work as required by this standard;
- 3) There is no authorised supervision of the adhesive bonding work.
- 4) The employees carrying out the adhesive bonding work at the practical level do not have valid qualification certificates as required by this standard;
- 5) Other conditions required by this standard are no longer fulfilled;
- 6) The period of validity has expired;
- 7) The user-company does not have certification.

The user company must confirm attention of the withdrawal in written form towards the certification body.

Distribution

- 1. Submitter (original)
- 2. Folder (copy)